

CODE 2
COMPANY SOURCE INSPECTION

Buyer inspection(s) of the articles or services purchased hereunder will be required prior to shipment from your plant. Inspection will be performed as designated by the Buyer and may be conducted during processing, fabrication, or as a final inspection.

When articles or services are ready for inspection, notify the Buyer's inspection representative and make available to him/her a copy of the related purchase order, applicable drawings, specifications, and changes thereto, related inspection and/or test equipment, and such other information as may be required to satisfactorily perform the quality assurance function required under this order.

Buyer's Source Inspection will use a Company furnished pre-planned document entitled "Procured Product Acceptance Requirements" (PPAR) or "Procurement Inspection Plan" (PIP), to accomplish company source inspection. The PPAR or PIP will be furnished to Seller. (The following product features constitute the need for establishing Buyers inspection points; e.g., prior to plating, assembly, or before commencement of functional testing. Contact the phone number below for clarification or the establishment of the requirements).

When interim or final Buyer Source Inspection is required, call (818) 586-2790 for inspection service required by this order. Rocketdyne reserves the right to waive inspection on all shipments. The intent to waive inspection shall be documented in writing from the Buyer or Quality Management and will be included with all shipments. Suppliers are required to provide Buyer the following information when requesting source inspection:

1. Part Number
2. Purchase Order number (last eight digits)
3. Type of inspection (interim or final)
4. Buyer's PPAR or PIP revision

Interim and final inspection points, designated by Code 2, shall be included on Seller's manufacturing and/or inspection instructions.

At the completion of the inspection a copy of the Procured Product Acceptance Requirement (PPAR) or Procurement Inspection Plan (PIPs) shall accompany the parts to the designated shipment destination. All other Data requirements shall be complied with.

Form code 2
Rev. 6/3/96
rsp/sec3

code2/word.ts